

# Multiconsult

## Rapportfilter

Til: 04.09.2017 08:37:00

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i %
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	04.09.2017 08:34:40	<b>13,40 mm/s</b>	<b>42</b>	<b>32%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	01.09.2017 17:46:58	<b>3,70 mm/s</b>	<b>42</b>	<b>9%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	01.09.2017 14:03:23	<b>17,30 mm/s</b>	<b>42</b>	<b>41%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	31.08.2017 13:39:38	<b>13,40 mm/s</b>	<b>42</b>	<b>32%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	30.08.2017 21:16:18	<b>3,20 mm/s</b>	<b>42</b>	<b>8%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	30.08.2017 19:10:31	<b>3,90 mm/s</b>	<b>42</b>	<b>9%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	30.08.2017 13:54:19	<b>11,00 mm/s</b>	<b>42</b>	<b>26%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	30.08.2017 07:59:50	<b>4,15 mm/s</b>	<b>42</b>	<b>10%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	28.08.2017 21:33:45	<b>3,60 mm/s</b>	<b>42</b>	<b>9%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	28.08.2017 19:00:20	<b>16,10 mm/s</b>	<b>42</b>	<b>38%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	28.08.2017 13:58:47	<b>4,80 mm/s</b>	<b>42</b>	<b>11%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	28.08.2017 08:06:22	<b>25,60 mm/s</b>	<b>42</b>	<b>61%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	25.08.2017 20:23:54	<b>4,70 mm/s</b>	<b>42</b>	<b>11%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	25.08.2017 10:53:06	<b>23,00 mm/s</b>	<b>42</b>	<b>55%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	25.08.2017 09:22:42	<b>20,40 mm/s</b>	<b>42</b>	<b>49%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	24.08.2017 18:11:07	<b>11,40 mm/s</b>	<b>42</b>	<b>27%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	24.08.2017 11:03:14	<b>37,50 mm/s</b>	<b>42</b>	<b>89%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	23.08.2017 20:59:55	<b>14,10 mm/s</b>	<b>42</b>	<b>34%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	23.08.2017 14:36:29	<b>43,10 mm/s</b>	<b>42</b>	<b>103%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	23.08.2017 10:28:09	<b>22,20 mm/s</b>	<b>42</b>	<b>53%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	23.08.2017 07:15:55	<b>4,75 mm/s</b>	<b>42</b>	<b>11%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	22.08.2017 20:58:08	<b>33,20 mm/s</b>	<b>42</b>	<b>79%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	22.08.2017 11:17:47	<b>23,00 mm/s</b>	<b>42</b>	<b>55%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	22.08.2017 07:57:19	<b>41,40 mm/s</b>	<b>42</b>	<b>99%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	21.08.2017 16:09:25	<b>22,20 mm/s</b>	<b>42</b>	<b>53%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	21.08.2017 14:45:49	<b>19,80 mm/s</b>	<b>42</b>	<b>47%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	21.08.2017 10:27:54	<b>46,40 mm/s</b>	<b>42</b>	<b>110%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	19.08.2017 12:34:08	<b>42,10 mm/s</b>	<b>42</b>	<b>100%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	19.08.2017 08:03:00	<b>37,60 mm/s</b>	<b>42</b>	<b>90%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	18.08.2017 18:15:34	<b>29,70 mm/s</b>	<b>42</b>	<b>71%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	18.08.2017 13:02:49	<b>37,20 mm/s</b>	<b>42</b>	<b>89%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	17.08.2017 21:35:25	<b>33,20 mm/s</b>	<b>42</b>	<b>79%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	17.08.2017 17:12:05	<b>31,10 mm/s</b>	<b>42</b>	<b>74%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	17.08.2017 11:10:32	<b>34,90 mm/s</b>	<b>42</b>	<b>83%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	16.08.2017 21:33:09	<b>30,50 mm/s</b>	<b>42</b>	<b>73%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	16.08.2017 14:48:05	<b>40,30 mm/s</b>	<b>42</b>	<b>96%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	16.08.2017 10:43:20	<b>42,00 mm/s</b>	<b>42</b>	<b>100%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	15.08.2017 21:42:49	<b>34,00 mm/s</b>	<b>42</b>	<b>81%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	15.08.2017 16:54:39	<b>29,20 mm/s</b>	<b>42</b>	<b>70%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	15.08.2017 10:03:59	<b>30,30 mm/s</b>	<b>42</b>	<b>72%</b>

## Multiconsult

K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	15.08.2017 07:02:19	<b>6,15 mm/s</b>	<b>42</b>	<b>15%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	14.08.2017 21:37:27	<b>29,30 mm/s</b>	<b>42</b>	<b>70%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	14.08.2017 10:44:46	<b>40,60 mm/s</b>	<b>42</b>	<b>97%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	11.08.2017 11:49:58	<b>40,90 mm/s</b>	<b>42</b>	<b>97%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	11.08.2017 08:07:49	<b>7,70 mm/s</b>	<b>42</b>	<b>18%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	10.08.2017 11:15:07	<b>62,90 mm/s</b>	<b>42</b>	<b>150%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	09.08.2017 16:01:32	<b>25,90 mm/s</b>	<b>42</b>	<b>62%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	08.08.2017 21:00:34	<b>36,80 mm/s</b>	<b>42</b>	<b>88%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	08.08.2017 16:03:45	<b>20,90 mm/s</b>	<b>42</b>	<b>50%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	07.08.2017 19:41:50	<b>31,60 mm/s</b>	<b>42</b>	<b>75%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	19.07.2017 16:20:33	<b>13,90 mm/s</b>	<b>42</b>	<b>33%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	19.07.2017 09:38:09	<b>41,80 mm/s</b>	<b>42</b>	<b>100%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	18.07.2017 07:55:05	<b>12,80 mm/s</b>	<b>42</b>	<b>30%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	17.07.2017 12:59:51	<b>43,10 mm/s</b>	<b>42</b>	<b>103%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	17.07.2017 08:20:10	<b>24,60 mm/s</b>	<b>42</b>	<b>59%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	15.07.2017 08:21:00	<b>30,50 mm/s</b>	<b>42</b>	<b>73%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	14.07.2017 16:42:33	<b>12,10 mm/s</b>	<b>42</b>	<b>29%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	14.07.2017 07:27:31	<b>56,70 mm/s</b>	<b>42</b>	<b>135%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	13.07.2017 17:43:57	<b>3,35 mm/s</b>	<b>42</b>	<b>8%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	13.07.2017 14:31:43	<b>12,50 mm/s</b>	<b>42</b>	<b>30%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	13.07.2017 08:45:41	<b>3,50 mm/s</b>	<b>42</b>	<b>8%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	12.07.2017 20:23:43	<b>62,20 mm/s</b>	<b>42</b>	<b>148%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	12.07.2017 14:19:05	<b>10,70 mm/s</b>	<b>42</b>	<b>25%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	11.07.2017 21:08:07	<b>41,90 mm/s</b>	<b>42</b>	<b>100%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	11.07.2017 11:26:48	<b>8,20 mm/s</b>	<b>42</b>	<b>20%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	10.07.2017 15:20:55	<b>4,90 mm/s</b>	<b>42</b>	<b>12%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	10.07.2017 10:08:24	<b>46,70 mm/s</b>	<b>42</b>	<b>111%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	07.07.2017 21:37:50	<b>13,80 mm/s</b>	<b>42</b>	<b>33%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	07.07.2017 16:53:06	<b>29,70 mm/s</b>	<b>42</b>	<b>71%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	07.07.2017 09:11:44	<b>4,05 mm/s</b>	<b>42</b>	<b>10%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	06.07.2017 10:38:24	<b>33,00 mm/s</b>	<b>42</b>	<b>79%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	05.07.2017 13:11:43	<b>5,85 mm/s</b>	<b>42</b>	<b>14%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	05.07.2017 13:04:08	<b>3,70 mm/s</b>	<b>42</b>	<b>9%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	05.07.2017 13:03:49	<b>4,70 mm/s</b>	<b>42</b>	<b>11%</b>
K11 MP-124	Grimseidvegen 37 Helgatun Barnehage	05.07.2017 08:51:47	<b>26,40 mm/s</b>	<b>42</b>	<b>63%</b>