

Multiconsult

Rapportfilter

Til: 21.12.2017 07:18:25

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av grei
K10 MP 40	Søre Titlestad 14	29.11.2017 20:56:29	3,25 mm/s	42	8%
K10 MP 40	Søre Titlestad 14	25.11.2017 13:20:06	3,55 mm/s	42	8%
K10 MP 40	Søre Titlestad 14	24.11.2017 12:50:26	3,45 mm/s	42	8%
K10 MP 40	Søre Titlestad 14	22.11.2017 09:31:58	3,15 mm/s	42	8%
K10 MP 40	Søre Titlestad 14	20.11.2017 19:20:23	4,25 mm/s	42	10%
K10 MP 40	Søre Titlestad 14	17.11.2017 13:16:24	4,65 mm/s	42	11%
K10 MP 40	Søre Titlestad 14	16.11.2017 15:28:43	7,40 mm/s	42	18%
K10 MP 40	Søre Titlestad 14	16.11.2017 07:41:52	4,70 mm/s	42	11%
K10 MP 40	Søre Titlestad 14	15.11.2017 11:58:54	5,10 mm/s	42	12%
K10 MP 40	Søre Titlestad 14	14.11.2017 11:30:30	5,35 mm/s	42	13%
K10 MP 40	Søre Titlestad 14	13.11.2017 13:52:40	6,15 mm/s	42	15%
K10 MP 40	Søre Titlestad 14	11.11.2017 13:35:41	6,05 mm/s	42	14%
K10 MP 40	Søre Titlestad 14	10.11.2017 14:16:19	6,30 mm/s	42	15%
K10 MP 40	Søre Titlestad 14	09.11.2017 18:41:44	8,65 mm/s	42	21%
K10 MP 40	Søre Titlestad 14	09.11.2017 11:48:55	9,00 mm/s	42	21%
K10 MP 40	Søre Titlestad 14	08.11.2017 17:37:32	8,25 mm/s	42	20%
K10 MP 40	Søre Titlestad 14	08.11.2017 10:02:18	10,50 mm/s	42	25%
K10 MP 40	Søre Titlestad 14	07.11.2017 15:26:47	7,85 mm/s	42	19%
K10 MP 40	Søre Titlestad 14	07.11.2017 09:03:43	11,20 mm/s	42	27%
K10 MP 40	Søre Titlestad 14	06.11.2017 17:27:25	10,90 mm/s	42	26%
K10 MP 40	Søre Titlestad 14	03.11.2017 11:17:10	13,10 mm/s	42	31%
K10 MP 40	Søre Titlestad 14	02.11.2017 18:14:59	14,00 mm/s	42	33%
K10 MP 40	Søre Titlestad 14	02.11.2017 11:20:08	10,10 mm/s	42	24%
K10 MP 40	Søre Titlestad 14	01.11.2017 13:55:12	11,10 mm/s	42	26%
K10 MP 40	Søre Titlestad 14	31.10.2017 20:47:03	13,50 mm/s	42	32%
K10 MP 40	Søre Titlestad 14	31.10.2017 13:16:32	13,00 mm/s	42	31%
K10 MP 40	Søre Titlestad 14	30.10.2017 20:03:02	16,80 mm/s	42	40%
K10 MP 40	Søre Titlestad 14	28.10.2017 10:19:54	14,20 mm/s	42	34%
K10 MP 40	Søre Titlestad 14	27.10.2017 18:50:16	13,80 mm/s	42	33%
K10 MP 40	Søre Titlestad 14	27.10.2017 11:49:11	10,80 mm/s	42	26%
K10 MP 40	Søre Titlestad 14	26.10.2017 16:17:31	7,95 mm/s	42	19%
K10 MP 40	Søre Titlestad 14	25.10.2017 12:40:57	7,95 mm/s	42	19%
K10 MP 40	Søre Titlestad 14	24.10.2017 19:18:14	8,95 mm/s	42	21%
K10 MP 40	Søre Titlestad 14	24.10.2017 11:55:37	9,50 mm/s	42	23%
K10 MP 40	Søre Titlestad 14	23.10.2017 15:48:25	7,70 mm/s	42	18%
K10 MP 40	Søre Titlestad 14	17.10.2017 18:34:04	8,25 mm/s	42	20%
K10 MP 40	Søre Titlestad 14	17.10.2017 11:07:47	5,25 mm/s	42	12%
K10 MP 40	Søre Titlestad 14	16.10.2017 15:38:35	5,50 mm/s	42	13%
K10 MP 40	Søre Titlestad 14	16.10.2017 09:09:34	5,05 mm/s	42	12%
K10 MP 40	Søre Titlestad 14	14.10.2017 12:18:48	6,60 mm/s	42	16%

Multiconsult

K10 MP 40	Søre Titlestad 14	13.10.2017 17:54:08	4,10 mm/s	42	10%
K10 MP 40	Søre Titlestad 14	12.10.2017 17:20:51	3,15 mm/s	42	8%
K10 MP 40	Søre Titlestad 14	12.10.2017 10:35:50	4,30 mm/s	42	10%
K10 MP 40	Søre Titlestad 14	11.10.2017 19:15:32	3,20 mm/s	42	8%
K10 MP 40	Søre Titlestad 14	10.10.2017 21:47:13	3,05 mm/s	42	7%
K10 MP 40	Søre Titlestad 14	10.10.2017 14:55:42	3,70 mm/s	42	9%