

Multiconsult

Rapportfilter

Til: 21.12.2017 07:19:46

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av gren
K10 MP 43	Søre Titlestad 2	12.12.2017 15:39:08	2,10 mm/s	42	5%
K10 MP 43	Søre Titlestad 2	11.12.2017 11:52:19	2,05 mm/s	42	5%
K10 MP 43	Søre Titlestad 2	10.12.2017 17:34:12	2,10 mm/s	42	5%
K10 MP 43	Søre Titlestad 2	08.12.2017 10:49:23	2,10 mm/s	42	5%
K10 MP 43	Søre Titlestad 2	07.12.2017 17:46:39	2,05 mm/s	42	5%
K10 MP 43	Søre Titlestad 2	05.12.2017 18:49:25	2,40 mm/s	42	6%
K10 MP 43	Søre Titlestad 2	05.12.2017 10:14:10	2,00 mm/s	42	5%
K10 MP 43	Søre Titlestad 2	01.12.2017 09:57:38	2,60 mm/s	42	6%
K10 MP 43	Søre Titlestad 2	30.11.2017 13:47:18	2,60 mm/s	42	6%
K10 MP 43	Søre Titlestad 2	29.11.2017 12:03:13	3,15 mm/s	42	8%
K10 MP 43	Søre Titlestad 2	28.11.2017 15:26:19	3,25 mm/s	42	8%
K10 MP 43	Søre Titlestad 2	27.11.2017 17:29:19	2,45 mm/s	42	6%
K10 MP 43	Søre Titlestad 2	25.11.2017 13:20:06	4,45 mm/s	42	11%
K10 MP 43	Søre Titlestad 2	24.11.2017 12:50:27	2,95 mm/s	42	7%
K10 MP 43	Søre Titlestad 2	23.11.2017 11:35:16	3,15 mm/s	42	8%
K10 MP 43	Søre Titlestad 2	22.11.2017 09:31:58	3,75 mm/s	42	9%
K10 MP 43	Søre Titlestad 2	20.11.2017 19:20:22	2,95 mm/s	42	7%
K10 MP 43	Søre Titlestad 2	17.11.2017 13:16:25	3,50 mm/s	42	8%
K10 MP 43	Søre Titlestad 2	16.11.2017 15:28:44	3,10 mm/s	42	7%
K10 MP 43	Søre Titlestad 2	16.11.2017 07:41:52	4,50 mm/s	42	11%
K10 MP 43	Søre Titlestad 2	15.11.2017 11:58:54	4,50 mm/s	42	11%
K10 MP 43	Søre Titlestad 2	14.11.2017 11:30:31	4,15 mm/s	42	10%
K10 MP 43	Søre Titlestad 2	13.11.2017 13:52:41	7,15 mm/s	42	17%
K10 MP 43	Søre Titlestad 2	11.11.2017 13:35:43	5,45 mm/s	42	13%
K10 MP 43	Søre Titlestad 2	10.11.2017 14:16:20	8,65 mm/s	42	21%
K10 MP 43	Søre Titlestad 2	09.11.2017 18:41:45	8,30 mm/s	42	20%
K10 MP 43	Søre Titlestad 2	09.11.2017 11:48:56	7,45 mm/s	42	18%
K10 MP 43	Søre Titlestad 2	08.11.2017 17:37:34	11,20 mm/s	42	27%
K10 MP 43	Søre Titlestad 2	08.11.2017 10:02:19	12,40 mm/s	42	30%
K10 MP 43	Søre Titlestad 2	07.11.2017 15:26:48	10,00 mm/s	42	24%
K10 MP 43	Søre Titlestad 2	07.11.2017 09:03:44	9,40 mm/s	42	22%
K10 MP 43	Søre Titlestad 2	06.11.2017 17:27:26	9,60 mm/s	42	23%
K10 MP 43	Søre Titlestad 2	03.11.2017 11:17:10	8,15 mm/s	42	19%
K10 MP 43	Søre Titlestad 2	02.11.2017 18:15:00	9,95 mm/s	42	24%
K10 MP 43	Søre Titlestad 2	02.11.2017 11:20:10	8,05 mm/s	42	19%
K10 MP 43	Søre Titlestad 2	01.11.2017 13:55:12	11,10 mm/s	42	26%
K10 MP 43	Søre Titlestad 2	31.10.2017 20:47:04	9,30 mm/s	42	22%
K10 MP 43	Søre Titlestad 2	31.10.2017 13:16:33	12,10 mm/s	42	29%
K10 MP 43	Søre Titlestad 2	30.10.2017 20:03:03	9,60 mm/s	42	23%
K10 MP 43	Søre Titlestad 2	28.10.2017 10:19:56	7,20 mm/s	42	17%

Multiconsult

K10 MP 43	Søre Titlestad 2	27.10.2017 18:50:17	5,45 mm/s	42	13%
K10 MP 43	Søre Titlestad 2	27.10.2017 11:49:12	7,65 mm/s	42	18%
K10 MP 43	Søre Titlestad 2	26.10.2017 16:17:32	4,40 mm/s	42	10%
K10 MP 43	Søre Titlestad 2	25.10.2017 12:40:58	3,75 mm/s	42	9%
K10 MP 43	Søre Titlestad 2	24.10.2017 19:18:16	6,35 mm/s	42	15%
K10 MP 43	Søre Titlestad 2	24.10.2017 11:55:38	5,35 mm/s	42	13%
K10 MP 43	Søre Titlestad 2	23.10.2017 15:48:27	5,00 mm/s	42	12%
K10 MP 43	Søre Titlestad 2	17.10.2017 18:34:05	4,20 mm/s	42	10%
K10 MP 43	Søre Titlestad 2	17.10.2017 11:07:49	3,25 mm/s	42	8%
K10 MP 43	Søre Titlestad 2	16.10.2017 15:38:37	2,85 mm/s	42	7%
K10 MP 43	Søre Titlestad 2	16.10.2017 09:09:35	2,65 mm/s	42	6%
K10 MP 43	Søre Titlestad 2	14.10.2017 12:18:48	3,85 mm/s	42	9%
K10 MP 43	Søre Titlestad 2	13.10.2017 17:54:08	2,20 mm/s	42	5%