

# Multiconsult

## Rapportfilter

Til: 23.11.2017 07:43:51

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av grei
K10 MP 37	Søre Titlestad 24	09.11.2017 11:49:00	<b>3,25 mm/s</b>	<b>42</b>	<b>8%</b>
K10 MP 37	Søre Titlestad 24	06.11.2017 17:27:27	<b>3,00 mm/s</b>	<b>42</b>	<b>7%</b>
K10 MP 37	Søre Titlestad 24	03.11.2017 11:17:12	<b>3,95 mm/s</b>	<b>42</b>	<b>9%</b>
K10 MP 37	Søre Titlestad 24	02.11.2017 18:15:02	<b>4,15 mm/s</b>	<b>42</b>	<b>10%</b>
K10 MP 37	Søre Titlestad 24	02.11.2017 11:20:12	<b>3,15 mm/s</b>	<b>42</b>	<b>8%</b>
K10 MP 37	Søre Titlestad 24	01.11.2017 13:55:14	<b>5,10 mm/s</b>	<b>42</b>	<b>12%</b>
K10 MP 37	Søre Titlestad 24	31.10.2017 20:47:06	<b>3,20 mm/s</b>	<b>42</b>	<b>8%</b>
K10 MP 37	Søre Titlestad 24	31.10.2017 13:16:35	<b>4,70 mm/s</b>	<b>42</b>	<b>11%</b>
K10 MP 37	Søre Titlestad 24	30.10.2017 20:03:04	<b>5,45 mm/s</b>	<b>42</b>	<b>13%</b>
K10 MP 37	Søre Titlestad 24	27.10.2017 18:50:17	<b>6,90 mm/s</b>	<b>42</b>	<b>16%</b>
K10 MP 37	Søre Titlestad 24	27.10.2017 11:49:13	<b>9,45 mm/s</b>	<b>42</b>	<b>22%</b>
K10 MP 37	Søre Titlestad 24	26.10.2017 16:17:32	<b>6,55 mm/s</b>	<b>42</b>	<b>16%</b>
K10 MP 37	Søre Titlestad 24	25.10.2017 12:40:59	<b>7,60 mm/s</b>	<b>42</b>	<b>18%</b>
K10 MP 37	Søre Titlestad 24	24.10.2017 19:18:16	<b>8,20 mm/s</b>	<b>42</b>	<b>20%</b>
K10 MP 37	Søre Titlestad 24	24.10.2017 11:55:39	<b>15,00 mm/s</b>	<b>42</b>	<b>36%</b>
K10 MP 37	Søre Titlestad 24	23.10.2017 15:48:26	<b>15,00 mm/s</b>	<b>42</b>	<b>36%</b>
K10 MP 37	Søre Titlestad 24	17.10.2017 18:34:05	<b>10,00 mm/s</b>	<b>42</b>	<b>24%</b>
K10 MP 37	Søre Titlestad 24	17.10.2017 11:07:48	<b>9,95 mm/s</b>	<b>42</b>	<b>24%</b>
K10 MP 37	Søre Titlestad 24	16.10.2017 15:38:37	<b>9,20 mm/s</b>	<b>42</b>	<b>22%</b>
K10 MP 37	Søre Titlestad 24	16.10.2017 09:09:34	<b>10,30 mm/s</b>	<b>42</b>	<b>25%</b>
K10 MP 37	Søre Titlestad 24	14.10.2017 12:18:47	<b>8,50 mm/s</b>	<b>42</b>	<b>20%</b>
K10 MP 37	Søre Titlestad 24	13.10.2017 17:54:07	<b>7,10 mm/s</b>	<b>42</b>	<b>17%</b>
K10 MP 37	Søre Titlestad 24	12.10.2017 17:20:50	<b>6,75 mm/s</b>	<b>42</b>	<b>16%</b>
K10 MP 37	Søre Titlestad 24	12.10.2017 10:35:51	<b>9,40 mm/s</b>	<b>42</b>	<b>22%</b>
K10 MP 37	Søre Titlestad 24	11.10.2017 19:15:32	<b>5,60 mm/s</b>	<b>42</b>	<b>13%</b>
K10 MP 37	Søre Titlestad 24	11.10.2017 12:57:45	<b>7,80 mm/s</b>	<b>42</b>	<b>19%</b>
K10 MP 37	Søre Titlestad 24	10.10.2017 21:47:12	<b>8,30 mm/s</b>	<b>42</b>	<b>20%</b>
K10 MP 37	Søre Titlestad 24	10.10.2017 14:55:42	<b>7,70 mm/s</b>	<b>42</b>	<b>18%</b>
K10 MP 37	Søre Titlestad 24	10.10.2017 08:47:43	<b>7,05 mm/s</b>	<b>42</b>	<b>17%</b>
K10 MP 37	Søre Titlestad 24	09.10.2017 16:57:40	<b>4,20 mm/s</b>	<b>42</b>	<b>10%</b>
K10 MP 37	Søre Titlestad 24	06.10.2017 09:48:18	<b>5,20 mm/s</b>	<b>42</b>	<b>12%</b>
K10 MP 37	Søre Titlestad 24	05.10.2017 12:27:18	<b>5,00 mm/s</b>	<b>42</b>	<b>12%</b>
K10 MP 37	Søre Titlestad 24	04.10.2017 15:00:43	<b>4,60 mm/s</b>	<b>42</b>	<b>11%</b>
K10 MP 37	Søre Titlestad 24	03.10.2017 17:53:04	<b>4,00 mm/s</b>	<b>42</b>	<b>10%</b>
K10 MP 37	Søre Titlestad 24	02.10.2017 19:12:41	<b>5,25 mm/s</b>	<b>42</b>	<b>12%</b>
K10 MP 37	Søre Titlestad 24	02.10.2017 08:58:17	<b>4,55 mm/s</b>	<b>42</b>	<b>11%</b>
K10 MP 37	Søre Titlestad 24	30.09.2017 09:05:01	<b>4,70 mm/s</b>	<b>42</b>	<b>11%</b>
K10 MP 37	Søre Titlestad 24	29.09.2017 12:24:29	<b>3,20 mm/s</b>	<b>42</b>	<b>8%</b>