



## Statens vegvesen

### Notat

Til:  
Fra: Statens vegvesen, Vegdirektoratet  
Kopi:

Saksbehandler/telefon:  
Henrik Vold / 22073216  
Vår dato: 22.04.2021  
Vår referanse: 21/47244-2

### NA Circular 2021 /06 – Update of specifications for use of sign 532 Lane ends in Manual N301E Work on and along roads

The Circular updates specification 3.2.5.3 regarding sign 532 Lane ends in Manual N301E Work on and along roads

#### Skilt 532 Kjørefelt slutter



532, V01



#### New specification:

This sign shall be used to warn road users that the lane ends when one of several lanes in the same direction is temporarily closed, unless documented risk assessments show that there is a better solution.

Where more than two lanes merge into one lane, the end of each individual lane shall be individually signed, unless documented risk assessments show that there is a better solution.

Lane endings should be done from left to right, unless documented risk assessments show that there is a better solution.

#### Replaced specification:

~~This sign shall be used to warn road users that the lane ends when one of several lanes in the same direction is temporarily closed. The sign requires that drivers in the lane that ends change lanes while yielding right of way.~~

Postadresse  
Statens vegvesen  
Vegdirektoratet  
Postboks 1010 Nordre Ål  
2605 LILLEHAMMER

Telefon: 22 07 30 00  
firmapost@vegvesen.no  
Org.nr: 971032081

Kontoradresse  
Brynsengfarete 6A  
0667 OSLO

Fakturaadresse  
Statens vegvesen  
Regnskap  
Postboks 702  
9815 Vadsø

~~Where more than two lanes merge into one lane, the end of each individual lane shall be individually signed.~~

~~In the interest of traffic safety, lane endings should be done from left to right.~~

The update does not authorise deviation from other specifications i N301E.

The update takes effect immediately and will be incorporated into the next revised version of N301E.