

# Multiconsult

## Rapportfilter

Til: 05.04.2018 07:52:20

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av gr
K10 MP 60	Fanavegen 292, Fjøs	10.03.2018 07:03:55	<b>3,80 mm/s</b>	<b>35</b>	<b>11%</b>
K10 MP 60	Fanavegen 292, Fjøs	09.03.2018 18:26:38	<b>3,85 mm/s</b>	<b>35</b>	<b>11%</b>
K10 MP 60	Fanavegen 292, Fjøs	09.03.2018 07:03:30	<b>3,25 mm/s</b>	<b>35</b>	<b>9%</b>
K10 MP 60	Fanavegen 292, Fjøs	08.03.2018 19:07:00	<b>5,05 mm/s</b>	<b>35</b>	<b>14%</b>
K10 MP 60	Fanavegen 292, Fjøs	08.03.2018 15:07:52	<b>4,15 mm/s</b>	<b>35</b>	<b>12%</b>
K10 MP 60	Fanavegen 292, Fjøs	08.03.2018 10:09:36	<b>5,00 mm/s</b>	<b>35</b>	<b>14%</b>
K10 MP 60	Fanavegen 292, Fjøs	07.03.2018 19:41:06	<b>5,05 mm/s</b>	<b>35</b>	<b>14%</b>
K10 MP 60	Fanavegen 292, Fjøs	07.03.2018 15:03:58	<b>5,70 mm/s</b>	<b>35</b>	<b>16%</b>
K10 MP 60	Fanavegen 292, Fjøs	07.03.2018 10:04:07	<b>5,40 mm/s</b>	<b>35</b>	<b>15%</b>
K10 MP 60	Fanavegen 292, Fjøs	06.03.2018 21:38:53	<b>7,95 mm/s</b>	<b>35</b>	<b>23%</b>
K10 MP 60	Fanavegen 292, Fjøs	06.03.2018 17:28:23	<b>10,60 mm/s</b>	<b>35</b>	<b>30%</b>
K10 MP 60	Fanavegen 292, Fjøs	06.03.2018 10:58:12	<b>11,80 mm/s</b>	<b>35</b>	<b>34%</b>
K10 MP 60	Fanavegen 292, Fjøs	05.03.2018 21:46:29	<b>9,20 mm/s</b>	<b>35</b>	<b>26%</b>
K10 MP 60	Fanavegen 292, Fjøs	05.03.2018 14:40:38	<b>17,80 mm/s</b>	<b>35</b>	<b>51%</b>
K10 MP 60	Fanavegen 292, Fjøs	03.03.2018 17:28:46	<b>19,30 mm/s</b>	<b>35</b>	<b>55%</b>
K10 MP 60	Fanavegen 292, Fjøs	03.03.2018 07:55:05	<b>11,10 mm/s</b>	<b>35</b>	<b>32%</b>
K10 MP 60	Fanavegen 292, Fjøs	02.03.2018 21:36:36	<b>13,30 mm/s</b>	<b>35</b>	<b>38%</b>
K10 MP 60	Fanavegen 292, Fjøs	02.03.2018 11:47:29	<b>22,30 mm/s</b>	<b>35</b>	<b>64%</b>
K10 MP 60	Fanavegen 292, Fjøs	01.03.2018 21:22:48	<b>18,10 mm/s</b>	<b>35</b>	<b>52%</b>
K10 MP 60	Fanavegen 292, Fjøs	01.03.2018 13:19:19	<b>22,90 mm/s</b>	<b>35</b>	<b>65%</b>
K10 MP 60	Fanavegen 292, Fjøs	28.02.2018 14:15:07	<b>23,30 mm/s</b>	<b>35</b>	<b>67%</b>
K10 MP 60	Fanavegen 292, Fjøs	27.02.2018 19:22:42	<b>28,60 mm/s</b>	<b>35</b>	<b>82%</b>
K10 MP 60	Fanavegen 292, Fjøs	27.02.2018 14:30:22	<b>21,80 mm/s</b>	<b>35</b>	<b>62%</b>
K10 MP 60	Fanavegen 292, Fjøs	26.02.2018 21:57:59	<b>13,40 mm/s</b>	<b>35</b>	<b>38%</b>
K10 MP 60	Fanavegen 292, Fjøs	26.02.2018 13:22:35	<b>14,60 mm/s</b>	<b>35</b>	<b>42%</b>
K10 MP 60	Fanavegen 292, Fjøs	24.02.2018 15:23:51	<b>9,10 mm/s</b>	<b>35</b>	<b>26%</b>
K10 MP 60	Fanavegen 292, Fjøs	22.02.2018 11:09:08	<b>5,95 mm/s</b>	<b>35</b>	<b>17%</b>
K10 MP 60	Fanavegen 292, Fjøs	21.02.2018 19:08:31	<b>6,60 mm/s</b>	<b>35</b>	<b>19%</b>
K10 MP 60	Fanavegen 292, Fjøs	21.02.2018 11:30:14	<b>6,25 mm/s</b>	<b>35</b>	<b>18%</b>
K10 MP 60	Fanavegen 292, Fjøs	20.02.2018 21:02:26	<b>4,55 mm/s</b>	<b>35</b>	<b>13%</b>
K10 MP 60	Fanavegen 292, Fjøs	19.02.2018 16:02:49	<b>6,70 mm/s</b>	<b>35</b>	<b>19%</b>
K10 MP 60	Fanavegen 292, Fjøs	19.02.2018 09:59:19	<b>4,45 mm/s</b>	<b>35</b>	<b>13%</b>
K10 MP 60	Fanavegen 292, Fjøs	17.02.2018 16:52:12	<b>3,10 mm/s</b>	<b>35</b>	<b>9%</b>