

Multiconsult

Rapportfilter

Til: 17.08.2017 12:06:04

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av greer
K11 MP 97	Grimseidvegen 25	15.08.2017 16:54:40	3,30 mm/s	42	8%
K11 MP 97	Grimseidvegen 25	14.08.2017 21:37:28	5,55 mm/s	42	13%
K11 MP 97	Grimseidvegen 25	11.08.2017 08:07:49	3,90 mm/s	42	9%
K11 MP 97	Grimseidvegen 25	09.08.2017 16:01:33	3,00 mm/s	42	7%
K11 MP 97	Grimseidvegen 25	08.08.2017 16:03:46	3,20 mm/s	42	8%
K11 MP 97	Grimseidvegen 25	19.07.2017 16:20:35	4,75 mm/s	42	11%
K11 MP 97	Grimseidvegen 25	18.07.2017 07:55:06	4,75 mm/s	42	11%
K11 MP 97	Grimseidvegen 25	17.07.2017 08:20:12	6,20 mm/s	42	15%
K11 MP 97	Grimseidvegen 25	14.07.2017 16:42:34	3,95 mm/s	42	9%
K11 MP 97	Grimseidvegen 25	13.07.2017 14:31:46	4,80 mm/s	42	11%
K11 MP 97	Grimseidvegen 25	12.07.2017 20:23:43	3,10 mm/s	42	7%
K11 MP 97	Grimseidvegen 25	12.07.2017 14:19:06	5,10 mm/s	42	12%
K11 MP 97	Grimseidvegen 25	11.07.2017 11:26:51	4,15 mm/s	42	10%
K11 MP 97	Grimseidvegen 25	10.07.2017 15:20:55	4,40 mm/s	42	10%
K11 MP 97	Grimseidvegen 25	06.07.2017 10:38:26	3,80 mm/s	42	9%
K11 MP 97	Grimseidvegen 25	05.07.2017 13:11:45	3,55 mm/s	42	8%
K11 MP 97	Grimseidvegen 25	05.07.2017 08:51:52	3,05 mm/s	42	7%
K11 MP 97	Grimseidvegen 25	04.07.2017 07:47:17	3,90 mm/s	42	9%
K11 MP 97	Grimseidvegen 25	03.07.2017 08:27:27	3,05 mm/s	42	7%
K11 MP 97	Grimseidvegen 25	30.06.2017 17:41:09	4,15 mm/s	42	10%
K11 MP 97	Grimseidvegen 25	22.06.2017 19:22:25	3,20 mm/s	42	8%