

Multiconsult

Målepunktrapport

616337-E39 K11 Rystelsesmåling

Rapportfilter		Til: 24.03.2017 07:00:46		Eksporter			Skriv ut	Lukk
Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av grense	Anmerkning		
K11 MP 47	Holtaåsen 13, Garasje	18.03.2017 14:45:19	3,10 mm/s	42	7%			
K11 MP 47	Holtaåsen 13, Garasje	07.03.2017 13:31:27	3,55 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	01.03.2017 21:00:20	3,10 mm/s	42	7%			
K11 MP 47	Holtaåsen 13, Garasje	01.03.2017 13:33:47	3,65 mm/s	42	9%			
K11 MP 47	Holtaåsen 13, Garasje	01.03.2017 08:33:10	4,05 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	27.02.2017 13:20:46	3,80 mm/s	42	9%			
K11 MP 47	Holtaåsen 13, Garasje	25.02.2017 08:01:48	4,10 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	23.02.2017 10:54:54	3,55 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	22.02.2017 13:17:29	3,55 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	22.02.2017 08:00:09	3,30 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	20.02.2017 12:19:39	3,30 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	17.02.2017 18:10:55	4,10 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	17.02.2017 13:08:52	4,05 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	16.02.2017 14:54:27	3,25 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	16.02.2017 08:13:20	4,10 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	14.02.2017 13:22:52	3,30 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	13.02.2017 15:11:24	5,95 mm/s	42	14%			
K11 MP 47	Holtaåsen 13, Garasje	10.02.2017 21:36:49	4,55 mm/s	42	11%			
K11 MP 47	Holtaåsen 13, Garasje	09.02.2017 11:22:53	4,75 mm/s	42	11%			
K11 MP 47	Holtaåsen 13, Garasje	08.02.2017 09:55:58	4,65 mm/s	42	11%			
K11 MP 47	Holtaåsen 13, Garasje	06.02.2017 21:23:40	6,10 mm/s	42	15%			
K11 MP 47	Holtaåsen 13, Garasje	06.02.2017 15:36:31	4,40 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	04.02.2017 09:26:24	3,55 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	03.02.2017 12:02:48	4,20 mm/s	42	10%			
K11 MP 47	Holtaåsen 13, Garasje	02.02.2017 08:27:06	4,55 mm/s	42	11%			
K11 MP 47	Holtaåsen 13, Garasje	31.01.2017 13:59:22	3,50 mm/s	42	8%			
K11 MP 47	Holtaåsen 13, Garasje	18.01.2017 18:39:08	3,10 mm/s	42	7%			
K11 MP 47	Holtaåsen 13, Garasje	16.01.2017 20:44:26	3,80 mm/s	42	9%			
K11 MP 47	Holtaåsen 13, Garasje	09.01.2017 11:28:31	3,30 mm/s	42	8%			