

Multiconsult

Rapportfilter Til: 19.09.2017 08:14:24

Målepunkt	Plassering	Dato	Verdi	Grense	Andel i % av gre
K11 MP-115	Steinsvikvegen 422	08.09.2017 17:34:00	3,10 mm/s	42	7%
K11 MP-115	Steinsvikvegen 422	22.08.2017 15:25:23	3,10 mm/s	42	7%
K11 MP-115	Steinsvikvegen 422	19.08.2017 15:10:31	3,65 mm/s	42	9%
K11 MP-115	Steinsvikvegen 422	18.08.2017 14:38:39	3,20 mm/s	42	8%
K11 MP-115	Steinsvikvegen 422	11.08.2017 17:18:09	4,55 mm/s	42	11%
K11 MP-115	Steinsvikvegen 422	14.07.2017 13:28:44	4,00 mm/s	42	10%
K11 MP-115	Steinsvikvegen 422	13.07.2017 18:33:10	4,30 mm/s	42	10%
K11 MP-115	Steinsvikvegen 422	12.07.2017 13:59:25	3,85 mm/s	42	9%
K11 MP-115	Steinsvikvegen 422	11.07.2017 16:39:34	4,40 mm/s	42	10%
K11 MP-115	Steinsvikvegen 422	10.07.2017 17:43:53	3,20 mm/s	42	8%
K11 MP-115	Steinsvikvegen 422	08.07.2017 11:02:52	4,00 mm/s	42	10%
K11 MP-115	Steinsvikvegen 422	05.07.2017 12:54:42	3,95 mm/s	42	9%
K11 MP-115	Steinsvikvegen 422	04.07.2017 15:10:07	3,30 mm/s	42	8%
K11 MP-115	Steinsvikvegen 422	30.06.2017 13:28:17	3,25 mm/s	42	8%