

Målepunkt	Plassering	Dato	Tid	Verdi	Enhet	Grense	Andel	Anmerkning
K10 MP 04	Svegane 1 Garasje	07.07.2016	08:02:24	4,85	mm/s	35	14	
K10 MP 04	Svegane 1 Garasje	06.07.2016	08:00:47	5	mm/s	35	14	
K10 MP 04	Svegane 1 Garasje	03.06.2016	17:16:44	3,2	mm/s	35	9	
K10 MP 04	Svegane 1 Garasje	01.06.2016	13:59:25	3,4	mm/s	35	10	
K10 MP 04	Svegane 1 Garasje	27.05.2016	15:23:19	3,15	mm/s	35	9	
K10 MP 04	Svegane 1 Garasje	26.05.2016	21:47:13	4,4	mm/s	35	13	
K10 MP 04	Svegane 1 Garasje	25.05.2016	18:15:54	13,9	mm/s	35	40	
K10 MP 04	Svegane 1 Garasje	24.05.2016	11:00:09	3,4	mm/s	35	10	
K10 MP 04	Svegane 1 Garasje	23.05.2016	15:45:38	3,95	mm/s	35	11	
K10 MP 04	Svegane 1 Garasje	21.05.2016	16:29:25	4,2	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	21.05.2016	08:59:21	4,2	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	20.05.2016	10:26:59	4,75	mm/s	35	14	
K10 MP 04	Svegane 1 Garasje	19.05.2016	12:41:18	3	mm/s	35	9	
K10 MP 04	Svegane 1 Garasje	14.05.2016	10:54:11	4,4	mm/s	35	13	
K10 MP 04	Svegane 1 Garasje	13.05.2016	10:12:36	4,55	mm/s	35	13	
K10 MP 04	Svegane 1 Garasje	12.05.2016	15:47:34	3,5	mm/s	35	10	
K10 MP 04	Svegane 1 Garasje	12.05.2016	09:36:40	5,9	mm/s	35	17	
K10 MP 04	Svegane 1 Garasje	11.05.2016	15:37:36	3,25	mm/s	35	9	
K10 MP 04	Svegane 1 Garasje	10.05.2016	18:29:53	7,65	mm/s	35	22	
K10 MP 04	Svegane 1 Garasje	10.05.2016	11:07:22	4,3	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	09.05.2016	15:06:48	7,35	mm/s	35	21	
K10 MP 04	Svegane 1 Garasje	09.05.2016	09:43:13	3,9	mm/s	35	11	
K10 MP 04	Svegane 1 Garasje	07.05.2016	10:24:57	8,65	mm/s	35	25	
K10 MP 04	Svegane 1 Garasje	06.05.2016	12:27:48	8,25	mm/s	35	24	
K10 MP 04	Svegane 1 Garasje	04.05.2016	16:55:29	13	mm/s	35	37	
K10 MP 04	Svegane 1 Garasje	03.05.2016	18:31:35	4,25	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	03.05.2016	10:35:12	9,1	mm/s	35	26	
K10 MP 04	Svegane 1 Garasje	02.05.2016	14:34:05	4	mm/s	35	11	
K10 MP 04	Svegane 1 Garasje	30.04.2016	15:47:31	7,3	mm/s	35	21	
K10 MP 04	Svegane 1 Garasje	29.04.2016	18:06:12	6,35	mm/s	35	18	
K10 MP 04	Svegane 1 Garasje	29.04.2016	16:02:23	4,15	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	29.04.2016	09:56:47	10,1	mm/s	35	29	
K10 MP 04	Svegane 1 Garasje	28.04.2016	17:12:23	4,5	mm/s	35	13	
K10 MP 04	Svegane 1 Garasje	28.04.2016	09:26:40	9,9	mm/s	35	28	
K10 MP 04	Svegane 1 Garasje	27.04.2016	13:23:26	3,75	mm/s	35	11	
K10 MP 04	Svegane 1 Garasje	25.04.2016	17:50:28	20,8	mm/s	35	59	
K10 MP 04	Svegane 1 Garasje	25.04.2016	10:32:10	5,1	mm/s	35	15	
K10 MP 04	Svegane 1 Garasje	23.04.2016	09:30:57	12,5	mm/s	35	36	
K10 MP 04	Svegane 1 Garasje	22.04.2016	16:17:02	5,9	mm/s	35	17	
K10 MP 04	Svegane 1 Garasje	22.04.2016	09:48:35	18,3	mm/s	35	52	
K10 MP 04	Svegane 1 Garasje	21.04.2016	13:47:34	4,8	mm/s	35	14	
K10 MP 04	Svegane 1 Garasje	21.04.2016	08:37:52	7,8	mm/s	35	22	
K10 MP 04	Svegane 1 Garasje	20.04.2016	09:16:27	8,05	mm/s	35	23	
K10 MP 04	Svegane 1 Garasje	19.04.2016	12:39:13	5,65	mm/s	35	16	
K10 MP 04	Svegane 1 Garasje	19.04.2016	09:14:55	4,75	mm/s	35	14	

K10 MP 04	Svegane 1 Garasje	18.04.2016	11:53:20	3,5	mm/s	35	10	
K10 MP 04	Svegane 1 Garasje	16.04.2016	14:20:56	6,1	mm/s	35	17	
K10 MP 04	Svegane 1 Garasje	15.04.2016	17:34:30	6	mm/s	35	17	
K10 MP 04	Svegane 1 Garasje	14.04.2016	16:53:22	6	mm/s	35	17	
K10 MP 04	Svegane 1 Garasje	13.04.2016	13:06:15	4,2	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	11.04.2016	18:35:14	4,25	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	09.04.2016	14:25:00	5,5	mm/s	35	16	
K10 MP 04	Svegane 1 Garasje	06.04.2016	10:59:28	8,05	mm/s	35	23	
K10 MP 04	Svegane 1 Garasje	04.04.2016	16:48:49	4,15	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	04.04.2016	11:58:58	6,65	mm/s	35	19	
K10 MP 04	Svegane 1 Garasje	01.04.2016	16:57:38	4,85	mm/s	35	14	
K10 MP 04	Svegane 1 Garasje	31.03.2016	12:57:51	4,7	mm/s	35	13	
K10 MP 04	Svegane 1 Garasje	30.03.2016	18:21:07	4,05	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	15.03.2016	11:32:32	4,35	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	09.03.2016	10:47:02	5,45	mm/s	35	16	
K10 MP 04	Svegane 1 Garasje	04.03.2016	13:47:08	7	mm/s	35	20	
K10 MP 04	Svegane 1 Garasje	03.03.2016	12:37:36	5,85	mm/s	35	17	
K10 MP 04	Svegane 1 Garasje	01.03.2016	13:58:54	4,3	mm/s	35	12	
K10 MP 04	Svegane 1 Garasje	29.02.2016	15:56:44	4	mm/s	35	11	



